


A red and white helicopter is shown in flight against a clear sky, positioned in the upper left quadrant of the page.A close-up photograph of a thick, braided steel cable. A red-painted metal shackle is attached to the cable, and another shackle is visible further down. The background shows a blurred view of a snowy mountain slope and a ski lift tower.


Aufruf der Rega

Projekt Remove:

Unbenötigte Kabel und Seile bitte melden!

A close-up of a yellow and black marker or signpost, likely used for marking hazards or specific locations in a mountainous area.

Seilbahnen und Kabel sind insbesondere für Helikopter, aber auch für Segelflugzeuge und Gleitschirme eine grosse Gefahr. Beschädigungen durch Kabel und Seile können gar zum Absturz eines Helikopters führen. Die Rega und die Armee rufen deshalb die Besitzer von nicht mehr benötigten Seilbahnen und/oder Kabeln auf, sich **bei der nächstgelegenen Rega-Basis oder** unter **Telefon 1414** zu melden. Die Luftfahrthindernisse werden ohne Kosten für deren Besitzer von Spezialisten der Armee und zivilen Partnern abgebrochen und entsorgt.

A close-up photograph showing a metal surface with several rivets. A cable is attached to the surface, and there is a visible hole or damage in the metal where the cable is secured.

*Weitere Exemplare des Infoblatts erhältlich bei:
Schweizerische Rettungsflugwacht (Rega), Rega-Center, Kommunikation,
Postfach 1414, 8058 Zürich-Flughafen*